

# PRESSURE LOSS CHART

## PRESSURE LOSS - HUNTER CONTROL ZONE KITS

ICZ-101-LF/-R		ICZ-101		ICZ-151-40-XL		ICZ-201-40-XL		PCZ-101		ACZ-075, ACZ-101	
Flow (GPM)	PSI Loss	Flow (GPM)	PSI Loss	Flow (GPM)	PSI Loss	Flow (GPM)	PSI Loss	Flow (GPM)	PSI Loss	Flow (GPM)	PSI Loss
2	3.0	2	3.0	20	2.0	20	2.5	1	2.0	1	2.0
5	5.0	5	5.0	40	3.0	40	4.0	5	5.5	5	5.5
10	8.0	10	8.0	60	8.0	60	6.5	10	9.0	10	9.0
15	11.0	15	11.0	80	13.5	80	10.0	15	13.0	15	13.0
-	-	20	12.0	-	-	100	11.0	-	-	-	-